Pages

CCR No. 96-0700H	3 Log	ged Date	11/05/96	Rev. B		Request	Type C	CR
Priority Routine	Urger	nt X Eme	ergency	Affected	Releas	se A	Change	Class II
Title (description) Update LaRC HW/Network Diagram (Document Number:420-TD-001-003)								
Documents Affected NONE				Source Nos (RID, NCR, Action Item, GSFC CCR, etc.) or Tech Reference				
RTM Change Start New Baseline								
Problem An additional IP network address bas been assigned by Ebnet for the Ingest ring at the LaRC DAAC to simplify maintainability								
Proposed Solution Update the LaRC HW/Network Diagram to reflect the address change. Update the configurations of the LaRC FDDI Switch at the two Ingest FDDI concentrators. Update the configuration of the four Ingest host machines								
<u> </u>		BOO Rel. B	Contracts [ESC		FOS [] N	M&O onts
Cost:	Nor	ne X	Small (Not exceeding \$	100,000)		dium 00 to \$500,000)		arge ver \$500,000)
Schedule: Additional LOC Materials	None		Other	Mar	n-Month	s		
Originator Jo Pulkinnen Signature							11/5/96 Date	
Office Rel A	Office Manager Narayan Prasad Signature for Manager							11/5/96 Date
Disposition Comments:	Approved X	Appro	oved w/Comm	ent	Forw	ard	Disappro	oved
(CCB Chairperso	n <u>N</u> arayaı Signature	n Parasad					11/5/96_

CM01JU96 ECS